

uBR10012ルータのMC3GX60Vラインカード間のライセンスのリホスト

内容

[概要](#)

[使用するコンポーネント](#)

[要件](#)

[手順](#)

[ステップ 1：デバイス資格情報の取得](#)

[ステップ 2：ライセンスポータルでのライセンス転送の要求](#)

[ステップ2.1ライセンス転送の送信元を指定する](#)

[ステップ2.2ライセンス転送のターゲットの指定](#)

[ステップ2.3ライセンス転送用の許可チケットの生成](#)

[ステップ 3：ソースLCのライセンスを取り消す](#)

[ステップ 4：ライセンスポータルでターゲットLCの新しいライセンスを取得](#)

[ステップ 4.1：リホスト情報を入力します](#)

[ステップ 4.2：ターゲットLCのライセンスファイルの生成](#)

[ステップ 5：ターゲットLCに新しいライセンスをインストールします。](#)

[ステップ 5.1：CMTSへのライセンスファイルのコピー](#)

[ステップ 5.2：ターゲットLCに新しいライセンスをインストールする前に、現在のライセンスステータスを確認します](#)

[ステップ 5.3：ターゲットLCへの新しいライセンスのインストール](#)

[ステップ 5.4：インストール後のライセンスステータスを確認します](#)

uBR10022(LC)2DS x 2 US8/172x608/0 16)

Shawn Dashuai Zhang & Andy Lau

Cisco uBR10012

MC3GC60V

[Cisco.com](https://www.cisco.com)

<https://slexui.cloudapps.cisco.com/SWIFT/LicensingUI/Quickstart#>

8/18/0

1LC

2

3LC

4LC

5LC

1

LC 8/181_cred.txt disk0 **more**

ubr10012-1#show license udi

SlotID	PID	SN	UDI

7/0	UBR-MC20X20V	CAT1441E0L2	UBR-MC20X20V:CAT1441E0L2
7/1	UBR-MC20X20V	CAT1441E0KH	UBR-MC20X20V:CAT1441E0KH
8/0	UBR-MC3GX60V	CAT1616E015	UBR-MC3GX60V:CAT1616E015

8/1 UBR-MC3GX60V CAT1435E0TZ UBR-MC3GX60V:CAT1435E0TZ ubr10012-1#license save credential
disk0:81_cred.txt subslot 8/1 Device credential saved to disk0:81_cred.txt ubr10012-1#**more**
disk0:81_cred.txt <?xml version="1.0" encoding="UTF-8"?><CISCO_WT_ARTIFACTS
version="1.0"><CISCO_WT_REHOST_ARTIFACT version="1.0"><HEADER><ARTIFACT_TYPE>Device
Credentials</ARTIFACT_TYPE><ARTIFACT_VERSION>1.0</ARTIFACT_VERSION><TRANSACTION_ID>T and I trans
id</TRANSACTION_ID><UDI><PID>UBR-
MC3GX60V</PID><SN>CAT1435E0TZ</SN></UDI><SOURCE>Device</SOURCE><CREATE_DATE>2013-07-
04T13:25:25.307Z</CREATE_DATE><ARTIFACT_INFO>T and art
info</ARTIFACT_INFO></HEADER><CONTENT><DECIPHER_INFO
encoding="BASE64">AAEAAgA0AA4AhQEBgABlBM8UMnw+NZxYfVwqIFuiq7aqRoKMf06/h0kQuoe706yxkteiCMZrEE592
0+SxD6TTEHBqlf9YHxgv6yguQ9hM+JXLASZRP5ijSyTfHc0eATvmwtLxEv17kMmIjpxMLZ7/tKd4AAAAAAAAAAAAAAAAAAAA
AAAAAAAAAAAAAAAAAAAA=</DECIPHER_INFO><CORE_DATA><CIPHER_DATA
encoding="BASE64">AAEAAgAPAA8DhAAPABAN/1bTrMxBGdHYqWuzbUD5rFvGVudf1BuINdnRKipAksB00Vs96Zw5U5tYt
xK0nixv11z1UTtvJhxzyK2r+lHG1UcZhn4ZPLIYwCJTMSpQpANPeI6rE324hkaT+NveeQxfVAp+uGu3/CKesJbfA3x0yqM
cevT2mUfC2aZY2LLbga9mv8dhNLSUTKN0uDGPChaHNw+VKXfLh0Y/rGurwVb63UsRKOIglef5Iw5bDHmZ6y2RiJy+VR7LvBZ
MZia1AouR0g7XiRwFjqG0MsahKrKTF+aMFBNBdHi0gZAYP7QnaiKNwsFHnU0Wky1EzqbCBYce6CBMMWDWLE30z68j/5roX1
m2cUHYEJAmGUBmChreBeEa44SHyQkTKQ1pv2213nhKv4PZ5cL5JIQs6xZMY6mcNj1f0uuUXIKswWrRj7T0GnQJCSB+cP9P0u
JIZ8cQrXopc1P+McA/TdNv9K0usJ0nUJZVCc2ZvS2B6XaLdAGssGbL0W3dlqyKpcushbLZ6s1F7h0vuQ4N56pScx0+PiE4VF
rz4G1U9JfWgt/G1hF359yNtaBBikxml37A5uwoDT5cMfLpJLJ48kWSi/9qunQ2mvmxxgRI+tMY3SxQtCx2GgmIPGNVTX8W1
hheo1DMRiLNYxmfrMP9vK27rcpsS4fEN2bK0hkaPDfmQDzx+/MsNS/38vSrHwKwRoe9xM0cAybyJgX7jr4hYed0F0g6QD+9U
vm8Ski0UMBmCaAZJHZJcgaC8BGvhZvbnDVPBoHql+8P1tL29YSFCg8GfJ1XHAMtqRB+kxZihVcRmD5eG6o70s2h/kt9oZteq
jMVraDEURxFY4SSr7WymL0a0e7WAP0rrCBUnMV18bkNW22Ju50eytNGHvKz9mjDfEfQmZegHrQJSQeMQD0h+UrRLS9qzpls8
5FL1sb6J7S1HvGMFdkTq3ITuqcmxMdgukZLP3prfWyc5ZaMtZ256B/ZdGiNowePzbvaFwUAYwQsLYDBrPmT80Bfm4SVekA6
ZSyexnkJevGipqW0Q0m9ATZqp1m60Lfwl0NpNTBVvv3Izin8M7h4SnAsRq59Kw5E4RgsraIgGyhtbDbEn6l09MegKb/hwErF
l054lz4DSfPdWUeiBrGziv9/D9fik6NZ2/v1v0ePYZTRehZLUk0JPlZwi8l7qRKZtBcHLXonc95q01w==</CIPHER_DATA>
</CORE_DATA><SIGNATURE_INFO
encoding="BASE64">AAEAAgALAAsAVAECAQnwYWA7F1UKowplFYRGINxVEf2ThwAAAAAAAAAAAAAAAAABImmNxd3wI3ESvX6T
CYfl8ffm9kRCY+zaQAc3ley0icVh5/4qa2t4Ns1iS+icrxrw==</SIGNATURE_INFO></CONTENT></CISCO_WT_REHOST_A
RTIFACT></CISCO_WT_ARTIFACTS> ubr10012-1#

2

[https://slexui.cloudapps.cisco.com/SWIFT/LicensingUI/Quickstart#web\[Devices\]>\[>\]\[Rehost license...\]\(1more\)](https://slexui.cloudapps.cisco.com/SWIFT/LicensingUI/Quickstart#web[Devices]>[>][Rehost license...](1more))

Product License Registration

Help Settings

Show: All Licenses for Yuen Tak Lau

PAKs or Tokens Licenses Devices Transactions History

Get Licenses ▾ | Move Licenses ▾ | Add Devices | Download Licenses | Email Selected Licenses | Export to CSV | Show Filters

☐	Device	Family	Features	Quantity
☐	UDI Product ID:UBR-MC3GX60V UDI Serial Number:	UBR MC20x20/3G60/PRE5/3GSPA	DS_License	123
			US_License	35
☐	UDI Product ID:UBR-MC20X20V UDI Serial Number:		US_License	20
			DS_License	20
			DS_License	+1 120
☐	UDI Product ID:C891FW-E-K9 UDI Serial Number:	800 Fixed	MEM-8XX-512U1GB	1
			advipservices	1

- Download License...
- Email License...
- Rehost license...
- Rehost license from failed device(RMA)...
- Get device information...

CCO[(Add Devices)]CCO

Initiate a Rehost

On this page, you can transfer specific licenses from one device to another that were previously registered with your Cisco.com profile or by others in your organization.
How do I ...

1. Specify License Source2. Specify Target & Options3. Review

Source Device Selection

Next

Transactions

License

search n

1

1.1

2

2.1

Next

Next

PAK

Search

search pak...

one

More...

one

More...

Select the product type

Device Credential

Credentials:

/hwErFI054Iz4DSfPdWUeiBrGziv9/D9fiK6NZ2
/v1vOePYZTRehZIukOJPlEZWl8I7qRKZlBcHLXonc95qO1w==</CIPHER_DATA>
</CORE_DATA><SIGNATURE_INFO
encoding="BASE64">AAEAAgALAAAsAVAECaQnwYWA7F1UKowplFYRGInxVEf2ThwAA
AAAAAAAAAAAAABlmmNxd3wI3ESvX6TCYfl8ffm9kRCY+zaQAc3leY0iCVh5/4qa2t4Ns1i
S+icrxy==</SIGNATURE_INFO></CONTENT></CISCO_WT_REHOST_ARTIFACT>
</CISCO_WT_ARTIFACTS>

OK

Cancel

Web

2.1

Source | Target | Review

UDI Product ID : UBR-MC3GX60V

UDI Ser

Enter Device Credentials

Selected Transaction requires Device Credential as its subgroup is Enabled with Rehost-
WithRevocation

Please Enter Device Credential in the below TextArea to Initiate Rehost [Click here for help](#)

```
<?xml version="1.0" encoding="UTF-8"?><CISCO_WT_ARTIFACTS version="1.0">
<CISCO_WT_REHOST_ARTIFACT version="1.0"><HEADER><ARTIFACT_TYPE>Device
Credentials</ARTIFACT_TYPE><ARTIFACT_VERSION>1.0</ARTIFACT_VERSION>
<TRANSACTION_ID>T and I trans id</TRANSACTION_ID><UDI><PID>UBR-MC3GX60V</PID>
<SN>CAT1616E015</SN></UDI><SOURCE>Device</SOURCE><CREATE_DATE>2017-09-
19T22:36:28.778Z</CREATE_DATE><ARTIFACT_INFO>T and art info</ARTIFACT_INFO>
</HEADER><CONTENT><DECIPHER_INFO
encoding="BASE64">AAEAAgAOAA4AhQEBgABIBMLu7b/Ai4y7fjihUrD4EcnDF6GCp5xAegEkU
dUNfr6rj6+zgOkHFntZYKmMPmBtSshMiTd3TI8q5PC8C37Tb+dAbINjNohKK87WvtY4tEaBXG
nb8+VHApSsRkd0zoOEclYYJeoAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA=
</DECIPHER_INFO><CORE_DATA><CIPHER_DATA
```

Outstanding Permission Tickets

No Outstanding Permission Tickets available.

OK

Cancel

Next

[Next]

2.2

[Quantity to Assign]

8/172DSX60US2DSx2US8/070DSx58US8/1

Subsidiary | Get New | Get Existing | Get Demo | **Transfer** | My Information | Related Tools

Initiate a Rehost

On this page, you can transfer specific licenses from one device to another that were previously registered with your Cisco.com profile or by others in your organization.
[How do I ...](#)

1. Specify License Source

2. Specify Target & Options

3. Review

Target Device and SKU Details

Enter the SKU quantity.

	Product Family	Product	SKU	Quantity Available	Quantity to Assign
1	UBR MC20x20/3G60	1 US license: Must configure with UBR-MC3GX60V only			
1.1			SWLIC-MC3GX60V-US	60	2
1.2			SWLIC-MC3GX60V-DS	72	2

Clear Quantities

Specify target details

UDI Product ID:

UDI Serial Number:

Back

Next

Cancel

[Next]

2.3

Initiate a Rehost



On this page, you can transfer specific licenses from one device to another that were previously registered with your Cisco.com profile or by others in your organization.
[How do I ...](#)

✓ 1. Specify License Source ✓ 2. Specify Target & Options **3. Review**

		Serial Number	Product ID
1	Source	CAT1435E0TZ	UBR-MC3GX60V
	Target	CAT1616E015	UBR-MC3GX60V

	Sku Name	Quantity
1.1	SWLIC-MC3GX60V-DS	2
1.2	SWLIC-MC3GX60V-US	2

Your License Key will be emailed within the hour to these email addresses and connected with the specified end user.

★ Send To:

★ End User:

★ License Agreement: ☒ I agree with the Terms of the License [View License Agreement...](#)

[Submit]

TFTPCMTS

```
ubr10012-1#copy tftp://10.66.94.155/CAT1435E0TZ_20130704171351238.lic disk0:
```

```
Destination filename [CAT1435E0TZ_20130704171351238.lic]?
```

```
Accessing tftp://10.66.94.155/CAT1435E0TZ_20130704171351238.lic...
```

```
Loading CAT1435E0TZ_20130704171351238.lic from 10.66.94.155 (via GigabitEthernet1/1/0): !
```

```
[OK - 8872 bytes]
```

3LC

Cisco IOS

license revoke

60

(disk0:rt)

```
ubr10012-1#license revoke disk0:CAT1435E0TZ_20130704171351238.lic disk0:rt Following Permanent
license(s) will be revoked from this device Feature Name: DS_License : Count = 72 Feature Name:
US_License : Count = 60 Following Permanent license(s) will be installed on this device Feature
Name: US_License : Count = 58 Feature Name: DS_License : Count = 70 Following Extension
license(s) will be installed on this device Feature Name: US_License : Count = 60 Feature Name:
DS_License : Count = 72 PLEASE READ THE FOLLOWING TERMS CAREFULLY. INSTALLING THE LICENSE OR
LICENSE KEY PROVIDED FOR ANY CISCO PRODUCT FEATURE OR USING SUCH PRODUCT FEATURE CONSTITUTES
YOUR FULL ACCEPTANCE OF THE FOLLOWING TERMS. YOU MUST NOT PROCEED FURTHER IF YOU ARE NOT WILLING
TO BE BOUND BY ALL THE TERMS SET FORTH HEREIN. You hereby acknowledge and agree that the product
feature license is terminable and that the product feature enabled by such license may be shut
down or terminated by Cisco after expiration of the applicable term of the license (e.g., 30-day
trial period). Cisco reserves the right to terminate or shut down any such product feature
electronically or by any other means available. While alerts or such messages may be provided,
```

it is your sole responsibility to monitor your terminable usage of any product feature enabled by the license and to ensure that your systems and networks are prepared for the shut down of the product feature. You acknowledge and agree that Cisco will not have any liability whatsoever for any damages, including, but not limited to, direct, indirect, special, or consequential damages related to any product feature being shutdown or terminated. By clicking the "accept" button or typing "yes" you are indicating you have read and agree to be bound by all the terms provided herein. ACCEPT? (yes/[no]): yes Rehost ticket saved to disk0:rt ubr10012-1#show license detail subslot 8/1 Index: 1 Feature: DS_License Version: 1.0 License Type: Evaluation License State: Active, In Use Evaluation total period: 8 weeks 4 days Evaluation period left: 8 weeks 3 days Expiry date: Sep 02 2013 06:41:34 License Count: 72/72/0 (Active/In-use/Violation) License Priority: High Store Index: 3 Store Name: Primary License Storage Index: 2 Feature: DS_License Version: 1.0 License Type: Permanent License State: Inactive License Count: 70/0/0 (Active/In-use/Violation) License Priority: Medium Store Index: 1 Store Name: Primary License Storage Index: 3 Feature: DS_License Version: 1.0 License Type: Evaluation License State: Inactive Evaluation total period: 8 weeks 4 days Evaluation period left: 1 week 2 days License Count: 72/0/0 (Active/In-use/Violation) License Priority: Low Store Index: 1 Store Name: Evaluation License Storage Index: 4 Feature: US_License Version: 1.0 License Type: Evaluation License State: Active, In Use --More-- % RPC failed to slot 17 Evaluation total period: 4 days Evaluation period left: 8 weeks 3 days Expiry date: Sep 02 2013 06:46:34 License Count: 60/60/0 (Active/In-use/Violation) License Priority: High Store Index: 2 Store Name: Primary License Storage Index: 5 Feature: US_License Version: 1.0 License Type: Permanent License State: Inactive License Count: 58/0/0 (Active/In-use/Violation) License Priority: Medium Store Index: 0 Store Name: Primary License Storage Index: 6 Feature: US_License Version: 1.0 License Type: Evaluation License State: Inactive Evaluation total period: 8 weeks 4 days Evaluation period left: 8 weeks 4 days License Count: 60/0/0 (Active/In-use/Violation) License Priority: Low Store Index: 0 Store Name: Evaluation License Storage ubr10012-1#

4LC

[Devices] > [Move licenses] > [Complete secure rehost...] UDI

PAKs or Tokens | Licenses | **Devices** | Transactions History

Get Licenses ▾	Move Licenses ▾	Add Devices	Download Licenses
☐	Device	Rehost selected licenses...	nily
☐	UDI Serial	Rehost from failed device(RMA)...	GW-10 DS384
	UDI Product	Complete secure rehost...	
		Share licenses... >	

```
ubr10012-1#more disk0:rt <?xml version="1.0" encoding="UTF-8"?><CISCO_WT_ARTIFACTS
version="1.0"><CISCO_WT_REHOST_ARTIFACT version="1.0"><HEADER><ARTIFACT_TYPE>Rehost
Artifact</ARTIFACT_TYPE><ARTIFACT_VERSION>1.0</ARTIFACT_VERSION><TRANSACTION_ID>00DD93AAAC</TRAN
SACTION_ID><UDI><PID>UBR-
MC3GX60V</PID><SN>CAT1435E0TZ</SN></UDI><SOURCE>Device</SOURCE><CREATE_DATE>2013-07-
04T13:41:34.151Z</CREATE_DATE><CISCO_REHOST_CHANGES><CISCO_REHOST_ADD><CISCO_WT_LICENSE
version="1.0"><FEATURE_NAME>US_License</FEATURE_NAME><FEATURE_VERSION>1.0</FEATURE_VERSION><UDI>
<PID>UBR-MC3GX60V</PID><SN>CAT1435E0TZ</SN></UDI><SOURCE>Cisco HQ</SOURCE><CREATE_DATE>2013-07-
05T00:13:44.000Z</CREATE_DATE><LICENSE_LINE_HASH
hashAlgo="SHA1">v/mLxNULGRGMRuR/vu09b2IRd2w=</LICENSE_LINE_HASH><TYPE>EXTENSION</TYPE><EXPIRATIO
N><DAYS>60</DAYS></EXPIRATION><EULA>YES</EULA><COUNT>60</COUNT></CISCO_WT_LICENSE></CISCO_REHOST
```

_ADD><CISCO_REHOST_ADD><CISCO_WT_LICENSE
version="1.0"><FEATURE_NAME>DS_License</FEATURE_NAME><FEATURE_VERSION>1.0</FEATURE_VERSION><UDI>
<PID>UBR-MC3GX60V</PID><SN>CAT1435E0TZ</SN></UDI><SOURCE>Cisco HQ</SOURCE><CREATE_DATE>2013-07-
05T00:13:44.000Z</CREATE_DATE><LICENSE_LINE_HASH
hashAlgo="SHA1">vXiItxKb5jUhXksJv0sdobszcyg</LICENSE_LINE_HASH><TYPE>EXTENSION</TYPE><EXPIRATIO
N><DAYS>60</DAYS></EXPIRATION><EULA>YES</EULA><COUNT>72</COUNT></CISCO_WT_LICENSE></CISCO_REHOST
_ADD><CISCO_REHOST_REMOVE><CISCO_WT_LICENSE
version="1.0"><FEATURE_NAME>DS_License</FEATURE_NAME><FEATURE_VERSION>1.0</FEATURE_VERSION><UDI>
<PID>UBR-MC3GX60V</PID><SN>CAT1435E0TZ</SN></UDI><SOURCE>Cisco HQ</SOURCE><CREATE_DATE>2010-11-
25T07:51:48.000Z</CREATE_DATE><LICENSE_LINE_HASH
hashAlgo="SHA1">GG9Lxrd1VJd0ihBN8FxbiV+y4f0</LICENSE_LINE_HASH><TYPE>PERMANENT</TYPE><COUNT>72<
</COUNT></CISCO_WT_LICENSE></CISCO_REHOST_REMOVE><CISCO_REHOST_REMOVE><CISCO_WT_LICENSE
version="1.0"><FEATURE_NAME>US_License</FEATURE_NAME><FEATURE_VERSION>1.0</FEATURE_VERSION><UDI>
<PID>UBR-MC3GX60V</PID><SN>CAT1435E0TZ</SN></UDI><SOURCE>Cisco HQ</SOURCE><CREATE_DATE>2010-11-
25T07:52:01.000Z</CREATE_DATE><LICENSE_LINE_HASH
hashAlgo="SHA1">djuYPaGE0/YcP/jdZdLBiPpERW8</LICENSE_LINE_HASH><TYPE>PERMANENT</TYPE><COUNT>60<
</COUNT></CISCO_WT_LICENSE></CISCO_REHOST_REMOVE><CISCO_REHOST_ADD><CISCO_WT_LICENSE
version="1.0"><FEATURE_NAME>US_License</FEATURE_NAME><FEATURE_VERSION>1.0</FEATURE_VERSION><UDI>
<PID>UBR-MC3GX60V</PID><SN>CAT1435E0TZ</SN></UDI><SOURCE>Cisco HQ</SOURCE><CREATE_DATE>2013-07-
05T00:13:44.000Z</CREATE_DATE><LICENSE_LINE_HASH
hashAlgo="SHA1">Z16GLxkzY5soZX+lff80dXud70Q</LICENSE_LINE_HASH><TYPE>PERMANENT</TYPE><COUNT>58<
</COUNT></CISCO_WT_LICENSE></CISCO_REHOST_ADD><CISCO_REHOST_ADD><CISCO_WT_LICENSE
version="1.0"><FEATURE_NAME>DS_License</FEATURE_NAME><FEATURE_VERSION>1.0</FEATURE_VERSION><UDI>
<PID>UBR-MC3GX60V</PID><SN>CAT1435E0TZ</SN></UDI><SOURCE>Cisco HQ</SOURCE><CREATE_DATE>2013-07-
05T00:13:44.000Z</CREATE_DATE><LICENSE_LINE_HASH
hashAlgo="SHA1">/6Xdchg0aVgYv9HFcDUtsuzqMDY</LICENSE_LINE_HASH><TYPE>PERMANENT</TYPE><COUNT>70<
</COUNT></CISCO_WT_LICENSE></CISCO_REHOST_ADD></CISCO_REHOST_CHANGES></HEADER><CONTENT><DECIPHER_
INFO
encoding="BASE64">AAEAAGAA0AA4AhQEBgABlBMh/Q5r7IwMdRBaS/JAFyDQEKGwQkgLtRFWfDza1cKxv3eZF/WVGvcBUBC
WkYMB5ULK/RAA0BkVdecBcHbPpE2LNaTVbI1zBAKw/B6iPnQIwIbGzfUTNsFkV3hKtVPBayWiG4boAAAAAAAAAAAAAAAAAAAA
AAAAAAAAAAAAAAAAAAAA=</DECIPHER_INFO><CORE_DATA><CIPHER_DATA
encoding="BASE64">AAEAAGAPAA8RtAAPABAanu6WfSp4fjmEfsILXTPN3nG/7QCtE2Saa+L9N3qAiqCF5QT1orKYqN8NTk
BZnYdSoDs003+n0Ek9c5kzTzxbtK2Qw+qtbAgS4L5ZwgM1WC5v8+muTuyAFefMglgXuG6rsoosn+7vkvaF02Au2I+wLvXg
TL9BYVMxrZixyk+aZYWL32z6GHF2P013xXLQk+nPovyB9Hy7/o8xBaVDZ+zYb2hUIB8osfvyqtyJP0S4u9V4Uwr22z2Vx1s
+GBw528i/tf3xB1+c3DtAWQfcAaPk5WPuB+KEYbJvhs/uSXqXwaQpDKxvQow5Im5+js4od5/whk0cq+OBLEXDGG7euBR+ra
azeP+7ULUN+zSY5yCNOe0wFJvLc4n/bQaAX8a38+KzKndJL8cI7LkyUgNxxv1KUgcaQYjaDstiwxanQ7ok87eVNMCTScK2Gq
Uxf0w4n1KWYDTW6Z0A3LzXwF+9uJZNzSTifBfRwE5rLsYlNpGbtLD0AmHpfKPazTuXadjrJoMLNwc+w52TK25dHhrRqWn4Pc
fwj5ce0hovPa6+XtsiTP+x/63xRf+0Bi5iihoCBAUm+mhn6xy2uhHDiIPkLaeY/no7E6Cyh7QS9gP9wFFyqBYJVq7n7qmGJG
ctdDZkTL9Q34RUDycvvrtrQnyf3nb0L3Nox5PxY7z0mxP2LldJ7A3+EsXFE06aw/c4Y9GgbB1g1Gfb6IAM9/HZWz4fYwVwC
LoZDL1CiBTWVLFWIGX49WTZqp9A//EMy0xCmEBbPEBiYifID19fRvJECVK8q39MsDY+VLR/li12idGJftiU1hLUQnoPYRIp
fpdSo4P5T+QxT6GIBSstXy55D1WlTealcw18o9h6XLlnUySTMZBmIHMH1MzevOgKRTaXJfMLhBTkiUl1NboVdbUKclc0PPEy
ely9XX19Z0LlTYNazAe4wbnxouDBsQ99WuxYpPr8TrCd+ab8vKX3DUFxu+pyznPVzcyMLTlkW2ZtsFZk4VjqU3xHBaZhhz2R
bdQckwlnkBB9+9e4eZ6wVOC29pVZBrBA8mh6Bt7H3dwj1LJNMpdegeZTgnr7+dHbATppbVeFFZe06WJ1jmm/EzRs/7/1mA01
uXUd6WUSjsyzUTIEyFTMwfb1un9uyMzoSzQbCerCz3vHQdi/dy8iQbXwGyJPKhjHbhBjiKN6+p1UXHzRGvr0r09v/kidTLn
fkBFgXP0oCRIiUMBuz/ULimzibTf0PfQwQ98r42dQwXgN4UPybKoR6/pqCPX287GVsB/5zpIvWR9544B+1Dvo+cCeuVA/60W
J3UFVqoCA9YNM6b+B6A4mZvBT78S+j+r+prNFMBzhnyD90y0OpY5Joc0EJfKdMSvDT78G+acfeqzRm76Ny4N4YbKVI4kUA06
PS0fqrSvK1hHUAu00ylVnqaD30X/SH8C97HCN1hmXUydz9ZfabAq49jaivrba7fLHYHFY56RaQUhjCK08v70CXyy+3zVWF9
Ce6YmAAjeTqVIE4Q6hZqXQbVLOUbl+YHoSVaUIfQ3LaJDi9phIrDlfpL9bYaCDDDCgarbj8Xh/CT+6qit1bXikoVSMlJ/xHD
EP9FFbL9oQQq0U90I4J6Hqcn/f0SD4wjiS86Rz6+EE6kNNg00FhVxQZQsZFABsHy6PFXF4sH2lr333ILEiAxlYpwUiANfkTU
ulF94rpdMKubQbPtjah1BnS1tCka3ANK5X0mDcmJ379K1l9zHs+s4B+I6/Dbb4kvZKUA++UPyzu/AxhlX0XGodRI419lvjtD
+rr3/kIJo0FkX3b1sx5qIdxgNsZmAG3ijUIxcMQmEnsJ7+/1zV7GCGfM9002E9BFqCVLzat0MKRKPU2aWM+Lp0Xvr9ybWjn0
Y4hIDR/3tnAYFo85ZAHTD00dyEHMaqx38fZuFHQ0vGKA+XZzhZy2qDG1SsAzN39VLDsDThkbgm5hM9seUHLvWin9QEsFzpe
bI6ENWIEz8vhlyWtfJZ5v/8KeBydSeTvYr9lro+02zSNfdrMmgulDGL04ZQ60358AnR7EBtN57WAYCrNJswyFySKSKQtHiZh
KVLmXiboXdwjCvquT8sLjk60iRtPtoboTRVHNCDBTardMonhHiy5ZY6DIKhg7DN/1no0APwNY8K4BZHTPyzb3P9BGg+tAiyt
Tzm0ulz/ktAweled7IU311RvS7wR3Wvxh7WTwiQG8e4fj+Fi0Tz90XBnBabl+7V53KHbcgXRC4w3wJmH804Gwe2UDVuyarFE
6uSbeZvf3FQitViC03h/gnGcvWtV6ghs0zwm7spxz2VNORK1KZRn+FmDPrTPBJeu6YN+VAFXVc27fJ/l0phJiRdomUW/VJgG
YGXZxC0wAZ0m9Mdht4w/nSsupcZQR0i0B4EPP06jnj6IJI5iNowSjqGdFQ0rIz9wTe06qvI33uunyq/jih8+g7qqwpzXncc70
gQ2hAO2Kynp4GjX5aUALbxs00diMjT2JUAH2aMoi7ZAqE9izK8wyPeZwDsD1GALfIedJEfQvUDFFewZDXEA4+JxHT0ybuK
j8KCZKMT0jhIOG6UgMuYr0rwl0/YAC3RSjVDCYiew2MpirnFJDS5TbQ6ua8YbVPjdJn+b4Wtfl29fV/mSPj3mZQCSf9k7M+
72Jy2b29Bqz/G0ZJB6+7+hXQRYVzB8XciS9bnPBWmt3JSKugotK65dqUTVoE9c+kPkmZ/HAUKST6FukqiZRE4mJYmgBJJyXM
YchJkv5HrUaJ8xfeB8+gJT40gbhaV2X6W2Yl22vVeV+epGPxU8VzBdQcltDoE6TU5YPqV8Pb7J/Z7KHF+QkcC1q91ZKCV7ob
9H4xvuBKsSGHS0HkI3/gzgrkM8fvaxWDC3RJk7C1iqd84Y17DxToCSmaFwymKaoRvK+iYxs1E6k4FdKrVobLvDiM+jZTcfuW
BD389nBuGmiDfVwIf5/DPuTJpXbPPPrCjCZZwUJF1K+ZjNjo09HLonY0mtP49T45+0uFBfd8w63rgTtx39N3itEJkEievSR
hkyB4ziL/gL60B9ssb/OYEMJoc+BIjuxLExyIonl4qN/x1B2Vm7AcfH6u0agaT/qTm+xsEe50ZDivuv4cr2zKdbQUiVXky1k

bfZGJDcOR41kh2eOeWYMKbHI9UipZ3mEgknBm+ZE6AUwYlRbZP3JrxUfNoXI73zIkCVZidzBYPVeKcBHxTRwnbXXqxz4kKn0
T0igchAdyh0gfsElsqWDcTRBreXHP3qT5syFSA7pydhTspK3BLMiWSuRZw9uH0bMJF8LURvnJD4hI1D1hLmFP4TD0v5bo2Mj
CgQmUSKaMfBu1XdB/0VawWrmdqXU/W4JIQUt96JNICl4BIZXtM2e8zWaziw4g83F8ND7v3fIFrvaReQL7K7Q+pZn7BbIpNG6
A5pMSJ79zChz+Da8JxZ5hxPhxjzt+SpXZ3Tz0SLP49B6WL6dti0cbIh854ekEDQRHwtDUMMtaYfdIBsureERzmUDLXHT73V
/+PIFMEKxwv6dDsR81qbs0yMT47DcCrcJwEvxxWds2Px30yuzA79FepsLvmK0udhm8Ik4zXuJfbDNdF00uV/P00LEQASUiuT
pLlm/L/YQ/3fd0nxtm823/n+FXksa4GX0ji+9qr7GmsEDo/sxPql0p4Ha+epmoYmiTKAJW7i9r+XLMTdpMXKriVgKIX6qydB
C5TGcKomeaAKVULkvHvCF80L/NyUdaSVg2cMcm7wWwarOrwHcjF7Wy/Kccbx0cgirYjgzXlU2REza+RRln+xy802IQDDaNBk
7ED6W1Dy9MKPknJc6vTJ+kf1bap0ag+Cm0GdGesgWJVRIMEk7UBJagChpP+eLPTmk6s7du9WLMVegBRMqIttqHhV0dZTo0lJ
Q1HGZFdvrgndd0V4kqDB0p28C0Y+Jci/V09waVfWHXsowL0hFXerFRYNNRvToXIdXug3uwKgVsL7QIKDwz3cKDb0CbbzR0VL
/Ydewk0BWYbqxZ6dIEGCKmYnXk2KJhxxz1QkkEw5JLvpYIPcR70iLVwr/nEH+CtWCG0fRiWVRPduCXU2Hrmq7hBv2c9+Fi6
V2TmWXWxrMBS3CflzTo06VLbL0Pt1G75b76D/ntzaCbco30/UtGkRv0Zhj3pwUd/oj4exSQ9SJrpashLYmGL9nAVz0M0oI3
p34L0yL3Y165zEEDuGQcsVd0ESxHf+81+7PwsY96+p5V70+vi10Jp4ia0B0gtddb2gic/gpxeKqCIyK6qaRwj6kIJRoFuaoVb
xBiZlU4Xmb818bBMm/zQDonW0ZFHVjtYukuqKdnbf20o2CY+Sf6HV3IMcrTTOMLL9xdeJbHZjHC7Y/PU7w4J0T6boDHFHv5Y
q2je90Dn5HzU/3wrXpvmLwbixVSDhphcdCEvKE8zUZuM0YHnn5uGn0YECiiQX4r2i7dBy7elocqeMFeMQLVo0S0jt0tZg0/
Is/J8hXHJv8xkRCSzVUYJBTRDb22vmpv5rbR805KQ8sBfXvILHbXQaj8Clu9Th6nRKbcEqGsDR1BQ941m4/aMyZe891tqe1l
uuJuIs7qXf00GKTb1+SliwW0kjzI5z8vR0bFTNGzif0/7qRCjad2+xf3dyR4zswJ28GZcUee1ni3Dwx/devKhPi4F1a+fTv1
EquDrkrYZdTAAxvGBjqqWPZCKK/32X1GTlwcBv9xNqSHY31IVME02FFwg1K/519RK5WAvB00a0oii7QYXiUQ3S5Znp2YUvRy
e7jGqL2zhixzor0D9W1DzGrVLjPfmW1aQ/hhv3SnCLrJ/Z45FLYJzWk6LQDGRan21d6MYnUgzwX033+Zx4KL59WgoGapGEfo
Qn56eolqE5ehaPCCWx09pJt1gTjitRR8e47iEX/fZ7rkYUfWxqBLBYyGP14WTMv1Q7N3VqYT6UIYj2Y028/SCUDKlhhKqPRi
wvJo3Hnb3jIokILNZNefu5tjFpU5quPV6Y2C1e1LfgUoHUIHTW/aP5Xlsbiu3uL1/QpmmFPmFeJjJ3ax0AYVo0s7pRmIWRo9
EvVyb7LFEElHnZoSyR2jIV1vx0wCCwB/tLPDDi9twc0ERdoMM+WFPCAZZEeBI7LfzZYT6djCmGbdg2C2wdoVNqENIT2P61nV
zQIJTEJfLktV7rVWHBaS9CesJxLX1nc1mJU6+lgFm9+a8QhEqvYx/4U4B54EYiXH2P3dxNhQbzemdR0ILuMjM3mF0ZK9zbwn
PTuEN87JTrQ1+UwXxHKSa/zPGROGjmCdYqIDeVm76HUDkgM7oQ0c4qD88LNKzc0UbKzbwJwTp9xymmajX9AnUe3h0QR1WVN
Lm9D6p4db5JSasUwBuxbB8obn/YLwB1Fi03bV0/tWSEdy/BWG9w6N2NcX4P+I1mmVk9t0Y0Qv74lVbuC9YuFbNy0zaFWY6qt
exC0dtmNbvuFIPCYznUbAYWeHzUbgwzAbLEtW6LPwKYpElkRsorXWL4p72NDK49w5kfBsYGWRd5C+/iJvzF9nnh5mBd5bg5l
ZTDiNB/aLd1M7QnkzAKI+42h1wWqBR/nmTf0N9cPQY4U8VepkliI2BHoZMW5IEQaRh1D1n0EpIa7hp/yloHln1eRJaBxo2Nz
CY8bQN61KVfXM+3/XC8D/M8bYn4zybUf3NmbQy+ES7p/AwrBwhdEhc3biHpKm0TdAdJa1kzaH8rOadqsenLWuWXVnHzIWgWb
uuUca5hTwfEaz0CuJAZDme+ETTSiHYCfBiZcoMuKfrJvqMdRRLId6w/1LYCCuAogxNTXzDYqjd79ujJnR/n5Mn/D7jOZtWd+
5P0tDC7g1lqh64zok+hKfropP2fuzU9wUkZqahjMG7/A5/IVGhn7y5k6MLx5IZDyRkKxAzYv0lhoGEojIpmd0wkymZVml2kL
HQRmmEE+y0TMwu74YyDapxCqguA3MckE6i/PGtpIW9+JhKTWA8tgMr7IrvLSsdLIIi02UVpa0aadEbnAtZP3y2i9YHCTbuJ
8kuBlw8t4mJMYe/ayR8E0w1+90</CIPHER_DATA></CORE_DATA><SIGNATURE_INFO
encoding="BASE64">AAEAAGALAAsAVAECAQLAYiZn2oL/b/XEYyF368la0v/kIQAAAAAAAAAAAAAAAAAE/cnMwLdddnDg807K
ZDqj7n5UvftxqDacwxmHnecgM3yfHlctTmyWC0lCdm9Mtt8g==</SIGNATURE_INFO></CONTENT></CISCO_WT_REHOST_A
RTIFACT></CISCO_WT_ARTIFACTS> ubr10012-1#

4.1

Safenet

UDIID: <PID>

UDI <SN>

[Rehost Ticket]

[Next]

Select the Product Type: Safenet

Enter a Rehost Ticket required to generate the license for the new device.

UDI Product ID:

UDI Serial Number:

Rehost Ticket:

<?xml version="1.0" encoding="UTF-8"?><CISCO_WT_ARTIFACTS version="1.0"><CISCO_WT_REHOST_ARTIFACT version="1.0"><HEADER><ARTIFACT_TYPE>Device Credentials</ARTIFACT_TYPE><ARTIFACT_VERSION>1.0</ARTIFACT_VERSION><TRANSACTION_ID>T and I trans id</TRANSACTION_ID><UDI>

4.2LC

[Get License]

Upload Rehost Ticket to Finish Rehost

Use this page to complete the final step of the secure license transfer process. [How do I ...](#)

?

	Serial Number	Product ID
1 Source	CAT1435E0TZ	UBR-MC3GX60V
Target	CAT1616E015	UBR-MC3GX60V

	SKU	Quantity	More Information	Feature
1.1	SWLIC-MC3GX60V-DS	2	1 DS license: Must configure with UBR-MC3GX60V only	DS_License
1.2	SWLIC-MC3GX60V-US	2	1 US license: Must configure with UBR-MC3GX60V only	US_License

Your License Key will be emailed within the hour to these email addresses and connected with the specified end user.

*Send To:

daszhang@cisco.com

+

*End User:

Zhang, Dashuai

*License Agreement:

☒ I agree with the Terms of the License

[View License Agreement...](#)

Back

Get License

Cancel

ステップ 5 : ターゲットLCに新しいライセンスをインストールします。

ステップ 5.1 : CMTSへのライセンスファイルのコピー

電子メールからuBR10Kからアクセス可能なTFTPサーバにライセンスファイルをコピーします。

TFTPサーバからuBR10Kにライセンスファイルをコピーします。

```
ubr10012-1#copy tftp://10.66.94.155/ CAT1616E015_20130704172627009.lic disk0:
```

```
Destination filename [CAT1616E015_20130704172627009.lic]?
```

```
Accessing tftp://10.66.94.155/CAT1616E015_20130704172627009.lic...
```

```
Loading CAT1616E015_20130704172627009.lic from 10.66.94.155 (via GigabitEthernet1/1/0): !
```

```
[OK - 2237 bytes]
```

```
2237 bytes copied in 0.556 secs (4023 bytes/sec)
```

```
ubr10012-1#
```

5.2LC

```
8/0
```

```
ubr10012-1#show license detail subslot 8/0
```

```
Index: 1      Feature: DS_License
```

```
Version: 1.0
```

```
License Type: Permanent
```

```
License State: Active, In Use License Count: 60/60/0 (Active/In-use/Violation) License  
Priority: Medium Store Index: 0 Store Name: Primary License Storage Index: 2 Feature: DS_License
```

Version: 1.0 License Type: Evaluation License State: Inactive Evaluation total period: 8 weeks 4 days Evaluation period left: 8 weeks 4 days License Count: 72/0/0 (Active/In-use/Violation) License Priority: None Store Index: 1 Store Name: Evaluation License Storage Index: 3 Feature: US_License Version: 1.0 License Type: Permanent License State: Active, In Use License Count: 16/16/0 (Active/In-use/Violation) License Priority: Medium Store Index: 1 Store Name: Primary License Storage Index: 4 Feature: US_License Version: 1.0 License Type: Evaluation License State: Inactive Evaluation total period: 8 weeks 4 days Evaluation period left: 8 weeks 4 days License Count: 60/0/0 (Active/In-use/Violation) License Priority: None Store Index: Name: Evaluation License Storage ubr10012-1#

5.3LC

ubr10012-1#license install disk0:CAT1616E015_20130704172627009.lic

Installing licenses from "disk0:CAT1616E015_20130704172627009.lic"

Installing...Feature:US_License...Successful:Supported

Installing...Feature:DS_License...Successful:Supported

2/2 licenses were successfully installed 0/2 licenses were existing licenses 0/2 licenses were failed to install

5.4

2x2show license detail8/062/18

ubr10012-1#

show license detail subplot 8/0

Index: 1 Feature: DS_License

Version: 1.0

License Type: Permanent

License State: Active, In Use License Count: 62/62/0 (Active/In-use/Violation) License Priority: Medium Store Index: 3 Store Name: Primary License Storage Index: 2 Feature: DS_License Version: 1.0 License Type: Permanent License State: Inactive License Count: 60/0/0 (Active/In-use/Violation) License Priority: Medium Store Index: 0 Store Name: Primary License Storage Index: 3 Feature: DS_License Version: 1.0 License Type: Evaluation License State: Inactive Evaluation total period: 8 weeks 4 days Evaluation period left: 8 weeks 4 days License Count: 72/0/0 (Active/In-use/Violation) License Priority: None Store Index: 1 Store Name: Evaluation License Storage Index: 4 Feature: US_License Version: 1.0 License Type: Permanent License State: Active, In Use License Count: 18/18/0 (Active/In-use/Violation) License Priority: Medium Store Index: 2 Store Name: Primary License Storage Index: 5 Feature: US_License Version: 1.0 License Type: Permanent License State: Inactive License Count: 16/0/0 (Active/In-use/Violation) License Priority: Medium Store Index: 1 Store Name: Primary License Storage Index: 6 Feature: US_License Version: 1.0 License Type: Evaluation License State: Inactive Evaluation total period: 8 weeks 4 days Evaluation period left: 8 weeks 4 days License Count: 60/0/0 (Active/In-use/Violation) License Priority: None Store Index: 0 Store Name: Evaluation License Storage ubr10012-1#

翻訳について

シスコは世界中のユーザにそれぞれの言語でサポート コンテンツを提供するために、機械と人による翻訳を組み合わせて、本ドキュメントを翻訳しています。ただし、最高度の機械翻訳であっても、専門家による翻訳のような正確性は確保されません。シスコは、これら翻訳の正確性について法的責任を負いません。原典である英語版（リンクからアクセス可能）もあわせて参照することを推奨します。