

Cisco Small Business

RV016, RV042, RV042G, RV082, RV320



Product: Cisco Small Business
ID: CVE-2023-20124
Affected Products: RV01x, rv32x, rce-nzAGWWDD
Published: 2023-04-05 16:00
Updated: 2023-04-05 20:30
Version: 1.1 (Final)
CVSS: 6.5
Workarounds: No workarounds available
Cisco ID: CSCwe67659, CSCwe67655

CVSS: 6.5 (Medium)
No workarounds available

Cisco Small Business

RV016, RV042, RV042G, RV082, RV320
This vulnerability affects Cisco Small Business routers (RV016, RV042, RV042G, RV082, RV320) running the Small Business Software (SBS) version 1.1. The vulnerability is a Denial of Service (DoS) attack that can be triggered by a specially crafted HTTP request. The attack vector is through the Web Management Interface (WMI) of the router. The vulnerability is caused by a buffer overflow in the WMI processing logic. The CVSS score is 6.5 (Medium). There are no workarounds available for this vulnerability. For more information, please refer to the Cisco Security Advisory at https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-sb-rv01x_rv32x_rce-nzAGWWDD.

CVSS: 6.5 (Medium)

CVSS: 6.5 (Medium)

Affects: Cisco Small Business routers (RV016, RV042, RV042G, RV082, RV320) running SBS version 1.1.

- RV016 Multi-WAN VPN
- RV042 Dual WAN VPN

翻訳について

シスコは世界中のユーザにそれぞれの言語でサポート コンテンツを提供するために、機械と人による翻訳を組み合わせて、本ドキュメントを翻訳しています。ただし、最高度の機械翻訳であっても、専門家による翻訳のような正確性は確保されません。シスコは、これら翻訳の正確性について法的責任を負いません。原典である英語版（リンクからアクセス可能）もあわせて参照することを推奨します。