# Bekijk 802.1x Extensible Authentication Protocol (EAP) verkeersstatistieken op SX500 Series Stackable Switches

## Doel

Om te zorgen voor meer methoden voor de authenticatie van host, worden plug-in modules ter beschikking gesteld voor klanten die toegang tot het netwerk hebben en voor verificatieservers, met behulp van het Extensible Authentication Protocol (EAP). Microsoft Windows gebruikt bijvoorbeeld EAP om verbindingen als externe VPN-toegang, inbelverbinding en site-to-site verbindingen te controleren. 802.1x/EAP verhindert dat een draadloze client het netwerk betreedt tenzij deze door de authenticatieserver geauthentiseerd is.

Dit artikel bevat informatie over de *MAP 802.1x*-pagina die gedetailleerde informatie bevat over de MAP-frames die worden verzonden of ontvangen.

### Toepasselijke apparaten

SX500 Series Stackable-switches

#### Softwareversie

• v1.3.0.62

### 802.1x MAP

Stap 1. Meld u aan bij het web configuratieprogramma en kies **Status en Statistieken > 802.1x EAP**. De *MAP 802.1x* pagina wordt geopend:

802.1x EAP					
Interface:	Unit/Slot 1/2 - Port	FE7 -			
Refresh Rate:	<ul> <li>No Refresh</li> <li>15 sec.</li> <li>30 sec.</li> <li>60 sec.</li> </ul>	FE1 A FE2 FE3 FE4 FE5 E FE6			
EAPOL Frames Received:	0	FE8			
EAPOL Frames Transmitted:	0	FE9 FE10			
EAPOL Start Frames Received:	0	FE11 FE12			
EAPOL Logoff Frames Received:	0	FE13			
EAP Response/ID Frames Received:	0	FE14 FE15			
EAP Response Frames Received:	0	FE16			
EAP Request/ID Frames Transmitted:	0	FE17 FE18			
EAP Request Frames Transmitted:	0	FE19 FE20 T			
Invalid EAPOL Frames Received:	0				
EAP Length Error Frames Received:	0				
Last EAPOL Frame Version:	0				
Last EAPOL Frame Source:	00:00:00:00:00				
Clear Interface Counters Clear All Interfaces Counters					

Stap 2. Kies de gewenste interface in de vervolgkeuzelijst Interface.

 Eenheids-/sleuf — De eenheid-ID van de eenheid (actief, lid, stand-by) in de stapel en het aantal uitbreidingssleuven dat beschikbaar is. Deze schakelaar ondersteunt maximaal 4 eenheden. Als u niet bekend bent met de gebruikte termen, raadpleegt u <u>Cisco Business:</u> <u>Lijst van termen van nieuwe termen</u>.

· Port — Kies in de vervolgkeuzelijst Poorten de juiste poort om te configureren.

802.1x EAP						
Interface:	Unit/Slot 1/2 - Port FE1 -					
Refresh Rate:	<ul> <li>No Refresh</li> <li>15 sec.</li> <li>30 sec.</li> <li>60 sec.</li> </ul>					

Stap 3. Klik op de radioknop die overeenkomt met de gewenste verfrissingssnelheid voor de statistieken in het veld Vernieuwingssnelheid.

- Geen verfrissing De pagina is nooit verfrissend.
- 15 seconden. De pagina wordt elke 15 seconden aangepast.
- 30 seconden. De pagina wordt elke 30 seconden aangepast.

• 60 seconden.— De pagina wordt elke 60 seconden opnieuw opgefrist.

Interface:       Unit/Slot       1/2       Port       FE1         Refresh Rate: <ul> <li>No Refresh</li> <li>15 sec.</li> <li>30 sec.</li> <li>60 sec.</li> </ul> EAPOL Frames Received:       0         EAPOL Frames Transmitted:       0         EAPOL Logoff Frames Received:       0         EAPOL Logoff Frames Received:       0         EAP Response/ID Frames Received:       0         EAP Request/ID Frames Transmitted:       0         EAP Request Frames Transmitted:       0         EAP Request Frames Received:       0         EAP Request Frames Received:       0         EAP Request Frames Transmitted:       0         Invalid EAPOL Frames Received:       0         Last EAPOL Frame Version:       0         Last EAPOL Frame Source:       0:0:00:00:00:00:00         Clear Interface Counters       Clear All Interfaces Counters	1	802.1x EAP					
○       15 sec.         ○       30 sec.         ○       60 sec.		Interface: Refresh Rate:	Unit/Slot 1/2 Port	FE1 💌			
EAPOL Frames Received:       0         EAPOL Frames Transmitted:       0         EAPOL Start Frames Received:       0         EAPOL Logoff Frames Received:       0         EAP Response/ID Frames Received:       0         EAP Response Frames Received:       0         EAP Request/ID Frames Transmitted:       0         EAP Request Frames Transmitted:       0         Invalid EAPOL Frames Received:       0         EAP Length Error Frames Received:       0         Last EAPOL Frame Version:       0         Last EAPOL Frame Source:       00:00:00:00:00:00			<ul> <li>15 sec.</li> <li>30 sec.</li> <li>60 sec.</li> </ul>				
EAPOL Frames Transmitted:       0         EAPOL Start Frames Received:       0         EAPOL Logoff Frames Received:       0         EAP Response/ID Frames Received:       0         EAP Response Frames Received:       0         EAP Request/ID Frames Transmitted:       0         EAP Request Frames Transmitted:       0         Invalid EAPOL Frames Received:       0         EAP Length Error Frames Received:       0         Last EAPOL Frame Version:       0         Last EAPOL Frame Source:       00:00:00:00:00:00		EAPOL Frames Received:	0				
EAPOL Start Frames Received:       0         EAPOL Logoff Frames Received:       0         EAP Response/ID Frames Received:       0         EAP Response Frames Received:       0         EAP Request/ID Frames Transmitted:       0         EAP Request Frames Transmitted:       0         Invalid EAPOL Frames Received:       0         EAP Length Error Frames Received:       0         Last EAPOL Frame Version:       0         Last EAPOL Frame Source:       00:00:00:00:00:00	I	EAPOL Frames Transmitted:	0				
EAPOL Logoff Frames Received:       0         EAP Response/ID Frames Received:       0         EAP Response Frames Received:       0         EAP Request/ID Frames Transmitted:       0         EAP Request Frames Transmitted:       0         Invalid EAPOL Frames Received:       0         EAP Length Error Frames Received:       0         Last EAPOL Frame Version:       0         Last EAPOL Frame Source:       00:00:00:00:00:00	I	EAPOL Start Frames Received:	0				
EAP Response/ID Frames Received:       0         EAP Response Frames Received:       0         EAP Request/ID Frames Transmitted:       0         EAP Request Frames Transmitted:       0         Invalid EAPOL Frames Received:       0         EAP Length Error Frames Received:       0         Last EAPOL Frame Version:       0         Last EAPOL Frame Source:       00:00:00:00:00:00	I	EAPOL Logoff Frames Received:	0				
EAP Response Frames Received:       0         EAP Request/ID Frames Transmitted:       0         EAP Request Frames Transmitted:       0         Invalid EAPOL Frames Received:       0         EAP Length Error Frames Received:       0         Last EAPOL Frame Version:       0         Last EAPOL Frame Source:       00:00:00:00:00:00	I	EAP Response/ID Frames Received:	0				
EAP Request/ID Frames Transmitted: 0 EAP Request Frames Transmitted: 0 Invalid EAPOL Frames Received: 0 EAP Length Error Frames Received: 0 Last EAPOL Frame Version: 0 Last EAPOL Frame Source: 00:00:00:00:00 Clear Interface Counters	I	EAP Response Frames Received:	0				
EAP Request Frames Transmitted:       0         Invalid EAPOL Frames Received:       0         EAP Length Error Frames Received:       0         Last EAPOL Frame Version:       0         Last EAPOL Frame Source:       00:00:00:00:00:00         Clear Interface Counters       Clear All Interfaces Counters	I	EAP Request/ID Frames Transmitted:	0				
Invalid EAPOL Frames Received: 0 EAP Length Error Frames Received: 0 Last EAPOL Frame Version: 0 Last EAPOL Frame Source: 00:00:00:00:00 Clear Interface Counters Clear All Interfaces Counters	I	EAP Request Frames Transmitted:	0				
EAP Length Error Frames Received: 0 Last EAPOL Frame Version: 0 Last EAPOL Frame Source: 00:00:00:00:00 Clear Interface Counters Clear All Interfaces Counters	I	Invalid EAPOL Frames Received:	0				
Last EAPOL Frame Version:       0         Last EAPOL Frame Source:       00:00:00:00:00:00         Clear Interface Counters       Clear All Interfaces Counters	I	EAP Length Error Frames Received:	0				
Last EAPOL Frame Source: 00:00:00:00:00 Clear Interface Counters Clear All Interfaces Counters	I	Last EAPOL Frame Version:	0				
Clear Interface Counters Clear All Interfaces Counters		Last EAPOL Frame Source:	00:00:00:00:00:00				

EAPOL is een verlengbaar verificatieprotocol via LAN. Dit is een protocol voor netwerkpoortverificatie. De volgende waarden worden weergegeven voor de interface:

• Ontvangen EAPOL-frames — Valid EAPOL-frames ontvangen op de gekozen haven.

• EAPOL-frames verzonden — Valid EAPOL-frames die door de gekozen haven worden doorgegeven.

- · Ontvangen EAPOL-startframes EAPOL-startframes ontvangen op de gekozen poort.
- · Ontvangen legoffecten legoff-frames die op de gekozen haven worden ontvangen.

• Ontvangen MAP-responsframe/ID-frames — MAP/ID-frames ontvangen op de gekozen poort.

• EAP-responsframes ontvangen — EAP-responsframes die door de gekozen poort worden ontvangen. Deze bevatten niet de ontvangen RESP/ID-frames.

• EAP-aanvraag/ID-frames verzonden — EAP Req/ID-frames die door de gekozen poort worden doorgegeven.

• EAP-aanvraagframes verzonden — EAP-aanvraagframes die door de gekozen poort worden doorgegeven.

• Ongeldige EAPOL-frames ontvangen — Niet-herkende EAPOL-frames ontvangen op de gekozen poort.

• MAP MAP MAG fout frames ontvangen — EAPOL-frames met een ongeldige lengte van pakkettekst ontvangen op de gekozen poort.

• Laatste EAPOL-versie — protocolversienummer toegevoegd aan het laatst ontvangen EAPOL-kader.

• Laatste EAPOL-frame-bron — bronMAC-adres gekoppeld aan het meest recent ontvangen EAPOL-frame.

Stap 5. (optioneel) Klik om de tellers van de gekozen interface te wissen op **Wis**interfacetellers.

Stap 6. (optioneel) Om de tellers van alle interfaces te wissen, klikt u op **Alle interfacetellers wissen**.