

Cisco WAP561 Wireless Access Points, Firmware Version 1.2.1.7

January 2019

These release notes describe the known issues for the Cisco WAP561 Wireless Access Points.

Requirements

- Your computer must meet the recommended hardware and software requirements.
- A computer with browser support for:
 - Internet Explorer v7.0 or later
 - Chrome v5.0 or later
 - Firefox v3.0 or later
 - Safari v3.0 or later

Software Component Update

- Openssl upgrade to version 1.0.2l
- NTP update to version 4.2.8p10

Enhancements

- Security enhancements

Related Information

Support	
Cisco Support Community	www.cisco.com/go/smallbizsupport
Cisco Support and Resources	www.cisco.com/go/smallbizhelp
Phone Support Contacts	www.cisco.com/go/sbssc
EU lot 26	For EU lot 26 related test result, please check this web page: www.cisco.com/go/eu-lot26-results
Cisco Firmware Downloads	www.cisco.com/go/smallbizfirmware Select a link to download firmware for Cisco Products. No login is required.
Cisco Open Source Requests	www.cisco.com/go/smallbiz_opensource_request
Cisco Partner Central (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Product Documentation	
Cisco WAP561 Administration Guide	www.cisco.com/go/500_wap_resources
Cisco Power Adapters	www.cisco.com/go/wap_accessories

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2019 Cisco Systems, Inc. All rights reserved.